



GARY R. HERBERT  
Governor  
SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES


MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Minerals Inspection Report

Report Date: 07/09/2014


Reviewed 

Mine Name: Round Valley Rock	Permit Number: M/029/0006 <sup>4</sup>	Mine Status: Active
Operator Name: Round Valley Rock, Inc.	Inspection Date: 07/31/2013	Permit Fees: Paid
Inspector(s): L. Heppler	Inspection Time: 1:30 PM	Bond Amount: \$67,200
Attendee(s): Rees Family	Weather: Sunny, Dry	Bond Escalation: 08/21/2012
Inspection Purpose: Routine annual inspection		Prior Inspection: 11/30/2010

### Conclusions and Recommendations

The Operator needs to stockpile topsoil, implement storm water runoff sediment ponds, both on a regular basis. Update the NOI to be more representative of which areas are currently being mined to those of which are reclaimed sections. It is recommended to stake and designate sections in conjunction with the bonded area where the work is in progress. OGM to continue annual inspections and monitor the site when in the area.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i> Bond escalation is past due as shown above.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i> No deficiencies were noted - project is gated	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i> No erosional problems noted, nor was there any evidence of any erosional problems.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i> No deleterious materials were noted on site	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i> Roads were maintained and in fair condition.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i> No concurrent reclamation was noted at the time of inspection, several older mining areas have been reclaimed.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i> No regrading at the site at the time of inspection, but mining was all near surface	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i> No soil stockpiles are noted at the time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i> Overall site vegetation is excellent	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i> This line is intentionally left blank	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Scott Rees- Round Valley Rock, Inc

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M029-Morgan/M0290004-RoundValley/inspection/TNSP-07312013.pdf





View of site from the valley



Dump - note head scarp cracking



Highwall



Highwall